



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program January 31, 2013

Reviewed: 

Mine Name: Henefer Landfill	Permit Number: S/043/0027
Operator Name: Interstate Brick Company	Inspection Date: November 03, 2010
Inspector(s): L Heppler	Time: 11:00 AM
Other Participants: Company Representative	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 10-31-2006 **Bond Amount:** \$179,960 (Held by Summit County) **Permit fee** is up to date

Purpose of Inspection: Routine annual inspection. This site was inspected as a small mine site on 12/04/2008 by Brett Gregory

Inspection Summary: Toured the landfill/mine and surrounding area. Summit County hold the bond for landfill. Large clay stockpile on site used for capping pit area which is utilized as a landfill.

Photos were taken to document site conditions.

Conclusions and Recommendations: Operator / DEQ / Summit County should review bond amount and update files on the site. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature 

LAH:eb

cc: John Hewitt - Interstate Brick Company

Summit County - Joe

DEQ - Division of Solid and Hazardous Waste

O:\M043-Summit\S0430027-HeneferLandfill\inspections\Insp-11032010.doc





Capped area – Landfill in background



Capped area – Landfill in background



Highwall – note property line along fence line



Stockpile for capping